

«PeakTech® P 3415» Digital multimeter, 6,000 counts, TrueRMS & USB



€74.90

Prices excl. VAT plus shipping costs and possibly lower value surcharge

Product number: P 3415

GTIN/EAN: 4250569400919

Description

The PeakTech 3415 is a handy and safe multimeter with a USB interface. It offers measurement functions for direct and alternating voltage, direct and alternating current measurement, resistance and many other measurement functions. The AC voltage and current measurement are recorded by the integrated real effective value (TrueRMS) function. With the USB interface it is possible to read any measured data and display it with the PeakTech DMM software.

Software: DMM Tool compatible - download in the service area

Technical features

- 3 5/6 digit backlit LCD display
- True RMS measurement (True RMS)
- Temperature measurement up to 1000 ° C
- Safety: EN 61010-1; CAT III 1000 V / CAT IV 600V
- Accessories: case, USB interface connection cable, software for Windows 98/2000 / XP / VISTA / 7/8/10, type K temperature wire sensor, temperature adapter, test leads, battery and manual

PeakTech Prüf- und Messtechnik GmbH

Gerstenstieg 4

DE-22926 Ahrensburg

www.peaktech.de

Specifications

USB: ■

Basic Accuracy DC: +/- 0,5%

Battery: 9V Block

Capacitance max.: 60 mF

Digital counts: 6.000

Display Type: LCD

NCV: ■

Over voltage category: CAT III 1000 V, CAT IV 600 V

Range selection: Auto

True RMS: ■

V DC max.: 1000V

A AC max.: 10A, 20 A

Hz max.: 1000 kHz

OHM max.: 60 MΩ

Temp. max.: 1000 °C

Temp. min.: -55 °C

mA DC max.: 600mA

mV DC max.: 600 mV

µA DC max.: 6000 µA

V AC max.: 750 V

mV AC max.: 600 mV

A DC max.: 10A, 20A

mA AC max.: 600 mA

µA AC max.: 6000 µA